## **Abstract**

5

A motor/alternator is formed by a single toroidal magnet and flux conductors which, in combination with flux switches, create an alternating magnetic circuit around a power coil. The motor/alternator geometry minimizes flux leakage. The form of the flux conductor and flux switch terminations allows for a high number of poles and reduces magnetic reluctance.